


⚠ CAUTION

Opening Cover could cause Electrical Shock

(Stealth Motor) The power cord *is* connected to an Internal Terminal Block



(PRO MAX Motor) The power cord *is not* connected to an Internal Terminal Block

